

# STATE OF VERMONT – DEPT. OF ENVIRONMENTAL CONSERVATION

Drinking Water & Groundwater Protection Division (DWGPD), 1 National Life Drive, Main Building – 2nd Floor,  
Montpelier, VT 05620-3251  
Tel. (802) 828-1535 or (802) 585-4907

## WELL COMPLETION REPORT

### WELL LOCATION

Well Owner or Purchaser: Eric Shaeffer  
E-911 Address: 389 Spruce Drive

WELL TAG No. 48933

Town: Andover  
Subdivision Name: Spruce Drive  
Lot Number: \_\_\_\_\_

### GEOGRAPHIC LOCATION (Complete A OR B, but not both)

Date Well Drilled: 6-26-2013

A. GPS Location: 28 N 43° 17' 55.7" W 072° 44' 03.8" 7  
Latitude Rdg. Longitude Rdg. GPS Make/Model # of Satellites Used (Min. 3)

B. Attach Town Map with well location marked, if not providing GPS location.

### WELL TYPE (Check one)


- ☒ Bedrock  
☐ Gravel  
☐ Monitoring  
☐ Other: \_\_\_\_\_

### WELL USE (Check one)

- ☐ Residential/Non-public  
☐ Public water system  
☐ Agricultural  
☐ Industrial  
☒ Other: pond

### REASON FOR WELL (Check one)

- ☐ New supply  
☐ Replace existing supply  
☐ Deepen existing supply  
☐ Additional supply  
☐ Test/exploration  
☐ Geothermal  
☒ Other: pond



### WELL CONSTRUCTION INFORMATION

#### DEPTHS

To bedrock 3 ft.  
Total 600 ft

#### CASING

Total Length 20 ft.  
Casing exposed 18 in.  
Diameter 7 in.  
Material Steel  
Weight 17 lb/ft

#### LINER OR INNER CASING

Total Length \_\_\_\_\_ ft.  
Depth to liner top \_\_\_\_\_ ft.  
Diameter \_\_\_\_\_ in.  
Material \_\_\_\_\_  
Weight \_\_\_\_\_ lb/ft  
Seal type \_\_\_\_\_

#### SCREEN DETAILS

Make/Type \_\_\_\_\_  
Material \_\_\_\_\_  
Diameter \_\_\_\_\_ in.  
Depth to screen top \_\_\_\_\_  
Slot size \_\_\_\_\_  
Gravel pack (type/size) \_\_\_\_\_

### WELL LOG

| From       | To         | Formation and water-bearing fracture Information |
|------------|------------|--------------------------------------------------|
| <u>0</u>   | <u>3</u>   | <u>Loam</u>                                      |
| <u>3</u>   | <u>20</u>  | <u>R- Gray silt</u>                              |
| <u>20</u>  | <u>110</u> | <u>R- Small fracture Gray silt</u>               |
| <u>110</u> | <u>560</u> | <u>R- Gray &amp; Black silt mica</u>             |
| <u>560</u> | <u>600</u> | <u>R- Gray &amp; Black silt mica</u>             |
|            |            |                                                  |
|            |            |                                                  |
|            |            |                                                  |

### SEALING METHOD

- ☒ Drive Shoe  
☐ Grouted – Grout type \_\_\_\_\_

### YIELD TEST

Tested for 1 hr @ 3 GPM  
Static Water Level 20 ft.  
(below land surface)  
☐ Overflowing? (check if yes)  
☐ Hydrofractured? \_\_\_\_\_ GPM

### WELL DRILLER INFORMATION

☒ Yes ☐ No; I provided property owner the Dept. of Health information, per 10 V.S.A. Section 1396(d)

Drilled by: Jody Townsend

Signature of Qualifying Individual  
Company: Host Wells & Pumps  
Lic # 23

### COMMENTS AND SITE SKETCH

Fracture at 110 feet 1-G.P.M.  
Fracture at 560 2-G.P.M.

White Copy - DWGPD

Yellow Copy - Owner

Pink Copy - Driller

1/10/13