

STATE OF VERMONT - DEPT. OF ENVIRONMENTAL CONSERVATION
Drinking Water & Groundwater Protection Division, 103 So. Main St., Waterbury, VT 05671-0403

Tel. (802) 241-3400

WELL COMPLETION REPORT

44449

WELL LOCATION

Well Owner or Purchaser: Ann Adams
E-911 Address: Adams rd. Pittsford, VT. 05763

WELL TAG No. 44449
(Fill In Number from Tag)

Town: Pittsford
Subdivision Name: _____
Lot Number: _____

GEOGRAPHIC LOCATION (Complete A OR B, not both)

Date Well Drilled: 11-15-12

A. GPS Location: 43°42'46" N 73°0'7.5" W
Latitude Rdg. Longitude Rdg. (OR)
GPS Make/Model _____ # of Satellites Used (Min. 3) _____

B. Attach a Town Map showing location of well with a dot.

WELL TYPE (Check One)

- ☒ Bedrock
☐ Gravel
☐ Monitoring
☐ Other: _____

WELL USE (Check one)

- ☒ Domestic
☐ Public
☐ Agricultural
☐ Industrial
☐ Other: _____

REASON FOR WELL (Check one)

- ☐ New Supply
☒ Replace Existing Supply
☐ Deepen Existing Supply
☐ Additional Supply
☐ Test/Exploration
☐ Other: _____

WELL CONSTRUCTION INFORMATION

DEPTHS

To Bedrock: 37' ft
Total: 205' ft

CASING

Total Length: 60' ft
Casing Exposed: 18' ft
Diameter: 6" in.

LINER OR INNER CASING

Total Length: _____ ft
Depth to Liner Top: _____ ft
Diameter: _____ in.
Material: _____
Weight: _____ lb/ft
Seal Type: _____

SCREEN DETAILS

Make/Type: _____
Material: _____
Diameter: _____ in.
Depth to Screen Top: _____ ft
Slot Size: _____
Gravel Pack (Type & Size): _____

SEALING METHOD

- ☒ Drive Shoe
☒ Grouted
Grout Type: Bent.

Material: Steel
Weight: 12 lb/ft

YIELD TEST

Tested for 1 hr. @ 50 GPM
Static Water Level 12' Ft. Below Land Surface
☐ (Check Here if Overflowing)
☐ Hydrofractured. Resulting flow= _____ GPM

WELL LOG

From To
0 37'
37' 60'
60' 129'
129' 205'

Formation Information and
Water Bearing Fractures

hardpan
limestone
limestone
Fractured Bed rock


WELL DRILLER INFORMATION

Drilled By: Wayne Angus
Company: Gus Breavitt Well Drilling Lic#: 258

Signature of Qualifying Individual

COMMENTS

SITE SKETCH (Optional)



FEB 08 2013

White Copy - WSD

Yellow Copy - Owner

Pink Copy - Driller

09/01/99