

STATE OF VERMONT - DEPT. OF ENVIRONMENTAL CONSERVATION
Water Supply Division, 103 So. Main St., Waterbury, VT 05671-0403 Tel. (802) 241-3400
WELL COMPLETION REPORT

WELL TAG No. 3191
(Fill In Number from Tag)

WELL LOCATION

Well Owner or Purchaser: Edward Thorndike Town: Benson
E-911 Address: 332 Frazier Hill Rd Subdivision Name: _____
Benson, VT Lot Number: _____

GEOGRAPHIC LOCATION (Complete A OR B, not both)

A. GPS Location: 45.20 12.0 N 073.5 W Magellan 4
Latitude Rdg. Longitude Rdg. GPS Make/Model # of Satellites Used (Min. 3)

(OR)

B. Attach a Town Map showing location of well marked with a clear dot.

WELL TYPE (Check One)

- ☒ Bedrock
☐ Gravel
☐ Monitoring
☐ Other: _____

WELL USE (Check one)

- ☒ Domestic
☐ Public
☐ Agricultural
☐ Industrial
☐ Other: _____

REASON FOR WELL (Check one)

- ☒ New Supply
☐ Replace Existing Supply
☐ Deepen Existing Supply
☐ Additional Supply
☐ Test/Exploration
☐ Other: _____

WELL CONSTRUCTION INFORMATION

DEPTHS

To Bedrock 12 ft
Total: 100 ft.

CASING

Total Length: 25 ft
Casing Exposed: 18 in.
Diameter: 6 in.
Material: Steel
Weight: 17 lb/ft

LINER OR INNER CASING

Total Length: _____ ft.
Depth to Liner Top: _____ ft.
Diameter: _____ in.
Material: _____
Weight: _____ lb/ft
Seal Type: _____

SCREEN DETAILS

Make/Type: _____
Material: _____
Diameter: _____ in.
Depth to Screen Top: _____ ft.
Slot Size _____
Gravel Pack (Type & Size): _____

SEALING METHOD

- ☒ Drive Shoe
☐ Grouted
Grout Type: _____

YIELD TEST

Tested for 1 hr. @ 3 GPM
Static Water Level _____ Ft. Below Land Surface
☒ (Check Here if Overflowing)
☐ Hydrofractured. Resulting flow= _____ GPM

WELL LOG

From	To	Formation Information and Water Bearing Fractures
<u>0</u>	<u>12</u>	<u>handpans large boulders</u>
<u>12</u>	<u>100</u>	<u>blue shale</u>

WELL DRILLER INFORMATION

Drilled By: P.A. Smith
Company: P.A. Smith Lic#: 40
Pentice A. Smith
Signature of Qualifying Individual

COMMENTS

SITE SKETCH (Optional)

