

Tel. (802) 241-3400

WELL TAG No. 23296

(Fill In Number from Tag)

E-911 Address: 1219 VT RT. 114

Lot Number:

7/04

Latitude Rdg.

Longitude Rdg

GPS Make/Model

of Satellites Used (Min. 3)

(OR)

WELL TYPE (Check One)☐ Other: _____

☒ Domestic
☐ Public
☐ Agricultural
☐ Industrial
☐ Other:

☐ Other:

☒ New Supply
☐ Replace Existing Supply
☐ Deepen Existing Supply
☐ Additional Supply
☐ Test/Exploration
☐ Other:

☐ Other: _____

To Bedrock 29 ft.
Total: 100 ft.

Total: 100 ft.

Total Length: 42 ft
Casing Exposed: 18 in.
Diameter: 6 in.
Material: Steel
Weight: 17 lb/ft

Weight: 17 lb/ft

☒ Drive Shoe
☐ Grouted
Grout Type

Grout Type:

~~Total Length : _____ ft.
Depth to Liner Top: _____ ft.
Diameter: _____ in.
Material: _____
Weight: _____ lb/ft
Seal Type: _____~~

Seal Type:

~~Make/Type: _____~~
~~Material: _____~~
~~Diameter: _____ in.~~
~~Depth to Screen Top: _____ ft.~~
~~Slot Size _____~~
~~Gravel Pack (Type & Size): _____~~

~~Gravel Pack (Type & Size):~~

Tested for 1 hr. @ 15 GPM

Static Water Level Ft. Below Land Surface

☐ (Check Here if Overflowing)☐ Hydrofractured. Resulting flow= _____ GPM

From	To
------	----

$$\begin{array}{r} 0 \\ 29 \end{array} \quad \begin{array}{r} 29 \\ 100 \end{array}$$

Formation Information and Water Bearing Fractures

T. 11 / HARD PAN
GRAY BROWNISH WATER

Drilled By Dr. Hunsate

Company: *Sensate Water* Lic#: *260*

Signature of Qualifying Individual

SITE SKETCH (Optional)

COMMENTS