

STATE OF VERMONT – DEPT. OF ENVIRONMENTAL CONSERVATION

Drinking Water & Groundwater Protection Division (DWGPD), 1 National Life Drive, Main Building – 2nd Floor,
Montpelier, VT 05620-3251
Tel. (802) 828-1535 or (802) 585-4907

WELL COMPLETION REPORT

WELL LOCATION

Well Owner or Purchaser: Fire Woodstock Station 2
E-911 Address: US Rt 4 W. Woodstock Rd.

WELL TAG No. 47778

Town: W. Woodstock
Subdivision Name: _____
Lot Number: _____

GEOGRAPHIC LOCATION (Complete A OR B, but not both)

A. GPS Location: 58.38° 43° 36.973' N 46.98° 72° 32.683' W Garmin 5
Latitude Rdg. Longitude Rdg. GPS Make/Model # of Satellites Used (Min. 3)

B. Attach Town Map with well location marked, if not providing GPS location.

WELL TYPE (Check one)

- ☒ Bedrock
☐ Gravel
☐ Monitoring
☐ Other: _____

WELL USE (Check one)

- ☐ Residential/Non-public
☐ Public water system
☐ Agricultural
☐ Industrial
☒ Other: _____

REASON FOR WELL (Check one)

- ☐ New supply
☒ Replace existing supply
☐ Deepen existing supply
☐ Additional supply
☐ Test/exploration
☐ Geothermal
☐ Other: _____

Received

OCT 03 2014

Drinking Water & Groundwater
Protection Division

WELL CONSTRUCTION INFORMATION

DEPTHS

To bedrock
56 ft.
Total
600 ft

CASING

Total Length 110 ft.
Casing exposed 20 in.
Diameter 6 in.
Material Steel
Weight 19 lb/ft

LINER OR INNER CASING

Total Length _____ ft.
Depth to liner top _____ ft.
Diameter _____ in.
Material _____
Weight _____ lb/ft
Seal type _____

SCREEN DETAILS

Make/Type _____
Material _____
Diameter _____ in.
Depth to screen top _____
Slot size _____
Gravel pack (type/size) _____

WELL LOG

From	To	Formation and water-bearing fracture Information
—	10	Gravel
10	56	Gray clay
56	78	Sept brown & black shale ledge
78	340	Solid black shale
340	430	Gray/black shale mix
430	480	black shale
480	485	Fractured black shale seam
485	600	Gray/black shale mix

SEALING METHOD

- ☒ Drive Shoe
☒ Grouted – Grout type Cement/Benzal grout mix
YIELD TEST at bottom 20' of casing
Tested for 1/2 hr @ 1pt SPM
Static Water Level 1 ft.
(below land surface)
☐ Overflowing? (check if yes)
☒ Hydrofractured? 6 GPM

WELL DRILLER INFORMATION

☒ Yes ☐ No; I provided property owner the Dept. of Health information, per 10 V.S.A. Section 1396(d)

Drilled by: Spear & Stark

Signature of Qualifying Individual
Company: Ottawaquechee Well Dr.
Lic # 213

White Copy - DWGPD

COMMENTS AND SITE SKETCH

Yellow Copy - Owner

Pink Copy - Driller

1/10/13

Property Line