

State of Vermont
Department of Environmental Conservation
Waste Management Division
103 South Main Street/West Building
Waterbury, VT 05671-0404
(802) 241-4528
FAX (802) 241-3296
tami.wuestenberg@state.vt.us

AGENCY OF NATURAL RESOURCES

April 10, 2007

Mr. Christopher Turley
TD Banknorth
90 Main Street
Montpelier, Vermont 05602

Re: Site Management Activity Complete (SMAC)
Former Danville Feed and Grain, Danville, Vermont
SMS Site #89-0348

Dear Mr. Turley:

The Vermont Department of Environmental Conservation, Sites Management Section (SMS) has received the Monitoring Well Abandonment Report from The Johnson Company, Inc. (JCO). The SMS has determined that the site is now eligible for a Site Management Activity Completed (SMAC) designation.

- Contamination was discovered at the site in June 1989 when five underground storage tanks (USTs) were removed from the site. Two gasoline USTs, one diesel UST and two fuel oil USTs. Reportedly, the contamination was encountered in the vicinity of the fuel oil USTs. Approximately 15 cubic yards of petroleum contaminated soil was polyencapsulated onsite during the UST removals.
- A Site Assessment was performed in September 1989 and consisted of the excavation of nine test pits; the installation of three groundwater monitoring wells; the collection and analysis of eleven soil and three groundwater samples; site surveying; slug testing; and a water supply and sensitive receptor survey. Results indicated that the bulk of petroleum contaminated soil was removed during the UST excavations; however several petroleum compounds were reported above the Vermont Groundwater Enforcement Standards (VGES) in two of the three wells.
- In November 1989, the SMS requested quarterly groundwater sampling and approved thinspreading of the contaminated soil stockpile. The SMS received notification on August 31, 1990 that the soils had been thinspread.
- Intermittent water quality sampling was performed at the site from 1991 through 2006. No groundwater exceedences were reported during the September 2006 water quality event, indicating natural attenuation has occurred at the site.

Based on the above, it appears that this site does not pose an unacceptable risk to human health or the environment. Therefore, the site has been assigned a Site Management Activity Completed (SMAC) designation. Sites which the Waste Management Division (WMD) has determined require no further management are given a SMAC. This designation does not release the owner of the property from any past or future liability which may arise from the contamination from the former USTs. The SMAC designation does mean that no further work is currently required at this site in response to the initial contamination.

Mr. Christopher Turley
April 10, 2007
Page 2 of 2

Please feel free to contact either Chuck Schwer or Tami Wuestenberg if you have any questions regarding the above.

Sincerely,



George Desch, Chief
Sites Management Section

cc: Danville Select Board
Danville Health Officer
Mr. James Bowes, JCO (*transmitted electronically*)
DEC Regional Office (*transmitted electronically*)