



East Mountain
Property Management Group

December 3, 1993

E. Matt Germon
Agency of Natural Resources
Dept. of Environmental Conservation
Hazardous Materials Management Division
103 South Main Street, West Building
Waterbury, VT 05671-0404

Re: Stockpiled soils at the former Rutland Group property,
Mendon, Vermont (site #93-1352)

Dear Mr. Germon,

The stockpiled soils at the above referenced site were spread out on site. The soils were spread out in the general location where the soils were stockpiled behind the North West corner of the garage building. Specifically, the spread out soils encompass an oblong shape approximately 45 by 25 feet in which the center is approximately 30 feet in a northwesterly direction from the corner of the garage. The soils were spread out to a depth of approximately 4 inches.

Don't hesitate to call if you have any questions.

Sincerely,

Ronald K. Bell
East Mountain Property Management

cc Robin Willey, V.P. Vermont National Bank

Tim Martin, Carrol George and Pratt