



Environmental Services of America, Inc.

JUL 15 11 10 AM '96

WASTE MANAGEMENT

ENSA Environmental, Inc.

205 Main Street
Brattleboro, VT 05302
Phone: (802) 254-3677
1-800-359-3677
Fax: (802) 254-7630

July 9, 1996

#1869

Left message for Paul
Miller 7/16/96 approving
this spreading ACS@ site.
Requested confirmation
letter so that site can
be considered for SMAC

Mr. Matthew Moran
Site Project Manager, Sites Management Section
Vermont Department of Environmental Conservation
Hazardous Materials Management Division
103 South Main Street/West Building
Waterbury, Vermont 05671-0404

RE: Redeemed Repair, Inc., 38 Main Street, North Bennington, Vermont

Dear Mr. Moran:

On June 3, 1996, a total of six excavations were made in the eight cubic yards of soil currently stockpiled at the above-referenced site. Each excavation was made to the base of the soil pile. The soil from each excavation was headspace screened per VT DEC protocol. The soil was screened with a ThermoEnvironmental Model 580B Organic Vapor Meter calibrated to a 250 ppm Isobutylene gas. The soil from each excavation showed non-detectable levels of volatile organic compounds. With your approval, the soil will be spread on-site at its place of origin (parking lot).

If you have any questions or require further information, please feel free to call me at 254-3677.

Sincerely,
ENSA Environmental, Inc.

Paul D.G. Miller
Hydrogeologist

cc: Steve Corcoran

\\950802\moran.let